


CORNER RECORD

Document Number 3034-A

City of _____ County of MERCED, California

Brief Legal Description N.E. Cor. Section 16 T.10S R.12E MDBEM



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey JUNE 5, 1990

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Fd. 3/4" I. PIPE WITH PLASTIC PLUG - LS FLUSH. FOUND FROM PREVIOUS TIES

A description of the physical condition of the monument as found and as set or reset: FOUND IN GOOD CONDITION EXCEPT LS NUMBERS ARE NOT LEGIBLE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 5 1990.

Signed Ralph N. Scheel, Jr. L.S. or R.C.E. Number LS3730
LIC. EXP. 6-30-92



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment COR. NO. 3034 A

N.E. Cor. Sect 16, T.10 S. R.12 E.
M.D.B. & M.

SET 'T' BAR CAP IN
SERVICE
POLE

SET CAL DOT 'T' BAR CAP
P. POLE

103.85

22.95

9

10

SET
+ IN SIDE OF
IRRIG VALVE
BOX

31.39

16

15

FOUND
3/4" I. PIPE
LS
FLUSH
NO RECORD

SAN JUAN ROAD

18.77

OPEN
DITCH

SET PK nails @ 2.00'