

#3110

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT June 24, 1980



Northwest corner of Lot 8, Block 17 (Section 17) of the Bliss Ranch Subdivision on file in Volume 7, Page 40, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

4" x 4" redwood @ ground line. Corner was destroyed during canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Reset from swing ties.
Set 1" O.D. x 15" ** iron pipe tagged R.C.E. 12700 @ 0.5 feet below ground line.

** pipe crossing below ground.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 53.94 Southeast from "X" on northeast side of 4" steel air valve pipe 10 ft. ± high.
- 25.58 East from "X" in top of southeast corner of structure.
- 29.34 West from "X" on top of southwest corner of structure.
- 53.70 Northeast from "X" on east side of 4" steel air valve pipe 10 ft. ± high.



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 25 June 1980
SIGNED: Frank C. Stambaugh
U.S. or R.C.E. No. 12700

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____
BY: _____
TITLE: _____
DOCUMENT No. 3110
STATEMENT ON BACK OF SHEET

SEAL

YES NO