

#3111

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E Mt. Diablo MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION -- DATE OF VISIT June 19, 1980



Northwest corner of Lot 4, Block 17 (Section 17) of the Bliss Ranch Subdivision on file in Volume 7, Page 40, M.C.R.

CORNER -- LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

4" x 4" redwood with nail in center @ ground surface. Corner was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


Set 1" x 28" galvanized iron pipe tagged R.C.E. 12700 35 feet south on the mid-section line at 0.6 feet below ground surface.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 35 foot offset to South
- 25.17 Northeast from "X" on top east edge of 42" standpipe.
- 102.19 Southeast from "X" on east side of 4" steel air valve pipe 10± feet high.
- 86.72 Southeast from "X" on east side of 30" standpipe.
- 28.1 East of north line of 4" steel air valves.

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 25 June No. 12700
 SIGNED: Frank C. Stambler
 L.S. or R.C.E. No.: 12700



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____
 BY: _____
 TITLE: _____
 DOCUMENT No. 3111
 STATEMENT ON BACK OF SHEET YES NO