

3123-C

CC IER RECORD

COUNTY OF Merced T 9 S R 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT April 21, 1976



Northwest Corner of Lot 9, Block 21 (Section 21) of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 46 of M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 4" x 4" redwood broken off at 1⁰ below ground line.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found 4" x 4" redwood that had been broken off and split. Wired both together and set 1" O.D. pipe with plug L.S. 4156 in center. Redwood is approximately 1.0 below ground; pipe set at ground line.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 35.96 Southwest from nail & shiner, set on 2 x 3 post.
- 31.12 Southwest from nail & shiner, set on 4 x 4 post.
- 52.80 Northwest from nail & shiner, set on 4 x 4 post.



SURVEYOR'S CERTIFICATE

CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 30, 1979.

SIGNED: *Johnny C. Davis*
L.S. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3123-C

STATEMENT ON BACK OF SHEET

YES NO