


#1 3124

CORNER RECORD

COUNTY OF Merced T 9 S R 15 E Mt. Diablo MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT August 22, 1978



Northwest Corner of Lot 5, Block 20 (Section 20) of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 45 of the M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1" O.D. pipe at 0⁹⁵ below ground.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found 1" O.D. pipe at 0⁹⁵ below ground with steel fence post 0¹ North of pipe. Set plastic plug marked L.S. 4156 top 1" O.D. pipe.


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

32.53 Southeast from South side of 36" standpipe.
69.35 Northeast from nail & shiner in power pole.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 30, 1979
L.S. 4156 SIGNED: *Johnny E. Davis*
L.S. or R.C.E. No. 4156



SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____
DOCUMENT No. 3124

STATEMENT ON BACK OF SHEET YES NO