


**CORNER RECORD**

Document Number 3317(2)

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description North 1/4 Corner Section 9, T. 8 S. R. 9 E., M. D. B. & M.



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey April 16, 2014

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found per Corner Record 3317 all ties not found. Also per PM 40-1.

A description of the physical condition of the monument as found and as set or reset: Monument was found in fair condition. Stamping unreadable due to corrosion. 1' diameter well set during repaving.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on MAY 13 2014  
Signed Bradley D. Buller P.L.S or R.C.E. No. L7659



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received MAY 20, 2014  
and examined and filed MAY 22, 2014  
Signed J. Steven Reichmuth P.L.S or R.C.E. No. 4895  
Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



KNIEBES ROAD

TO GUSTINE

CENTRAL YOSEMITE HWY  
SR 140

SET PK WITH  
BRASS CALTRANS WASHER  
IN UTILITY POLE

69.34'

FND 2" IP WITH THREADED  
PIPE CAP SET IN PCC  
ASSUMED CENTER CORRODED  
STAMPING UNREADABLE  
SET WELL DN 0.35'

13.55'

43.38'

SET PK WITH  
BRASS CALTRANS WASHER  
IN NEW UTILITY POLE

FND 1" IP WITH  
TAG "LS 3664"

KNIEBES ROAD