


3425

CO' ER RECORD

COUNTY OF Merced T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []
CORNER IDENTIFICATION — DATE OF VISIT September 7, 19 76



Southeast corner, Block 15 (Section 15) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of Plats page 39 M.C.R.

CORNER — LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 5/8" rod at 1² below road surface.
Set 60^D nail at road surface.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found pro-rated section corner 1-1/4" O.D. pipe with possible railroad spike in center at 1¹⁵ below road surface. Set 2 x 2 with nail at road surface. 27.47 North of 5/8" rod block corner.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 39.46 Northeast of nail & shiner in power pole.
- 64.48 Northeast of nail & shiner in power pole.
- 178.28 Northwest of nail & shiner in telephone pole.
- 2.00 Swing ties North & West.
- 27.47 South of 1-1/4" O.D. pipe pro-rated corner.



SURVEYOR'S CERTIFICATE

JOHNNY E. DAVIS
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
LS. 4156 January 29, 19 79
SIGNED: *Johnny E. Davis*
R.C.E. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____
DOCUMENT No. 3425
STATEMENT ON BACK OF SHEET
YES [] NO []