


**CORNER RECORD**

Document Number 3461

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N.E. COR. SECT. 16, T.10S., R.11E., MDB&M.



**CORNER TYPE**

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 6-7-90

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Fd. 2' RP'S, Fd 3/4" I. PIPE WITH PLASTIC PLUG LS 4156 - NO REF.


A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

MONUMENT APPEARS TO BE IN GOOD CONDITION, DOWN 0.5'

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 7 1990.

Signed Ralph N. Scheel L.S. or R.C.E. Number LS 3730  
LIC EXP 6-30-92



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor

County Surveyor's Comment COR. NO 3461





TIOS R.I.E  
MOB&M

SET PR&SHNER  
IN P. POLE

180.12

DELTA

ROAD

2639.65 (M)

285.69'

68.97

76.63

70.38

SET  $\nabla$  ON SIDE OF  
STEEL PIPE  
GATE POSTS

FOUND  
3/4" I. PIPE DOWN OF  
PLASTIC PLUG LS 4156  
2' RPS LS 4156  
SET SPIKE AT  
SURFACE  
NO REFERENCES

FND CARSONITE MARKER  $\nabla$   
SCRIBED  $\frac{9}{10}$   
 $\frac{16}{15}$

(LAST POLE AT  
END OF LINE -  
TRANS. & DROP TO  
RESIDENCE)

SET  
PR&SHNER  
IN P. POLE

1/4 COR. FD 3/4" I. PIPE  
LS 4150

