


# CORNER RECORD

Document Number 3462

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description E. 1/4 COR. SEC. 16, T. 10 S. R. 10 E



### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Monument shown on Record of Survey Vol. 20 Pg. 42  
Monument well set over 3/4" iron pipe (SEE REVERSE SIDE FOR SWING TIES)  
POINTS TIED OUT NOVEMBER, 1996 PRIOR TO PAVING EFFORT BY  
MERCED COUNTY, MONUMENT WELL SET AFTER PAVING.

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE  
FOR THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO  
CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES  
SHOWN HEREON TO TRUE BOUNDARY LOCATIONS

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.

Signed Roy L. Turney L.S. or ~~P.C.E.~~ Number 5523



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

T. 10 S. R. 11 E.

