


**CORNER RECORD**

Document Number 3462

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description E. 1/4 COR. SECT 16, T. 10S. R. 11E. MDBEM



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 6-7-90

**COORDINATES  
(Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 3/4" I. PIPE WITH PLASTIC PLUG LS4150, DOWN 0' 2' RPS - S&E WITH LS TAGS LS4156

A description of the physical condition of the monument as found and as set or reset: MONUMENT APPEARS TO BE IN GOOD CONDITION

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 7 1990.

Signed Ralph N. Scheel L.S. or R.C.E. Number LS 3730  
LIC EXP 6-30-92



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Deputy Co. Surveyor

County Surveyor's Comment COR. #3462



16  
15

TIOS RIE  
MOBEM

