


CORNER RECORD

Document Number 3512

City of _____

County of Merced, California

Brief Legal Description Northwest corner of Section 7, Township 7 South,
Range 15 East M.D.B.&M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Date of Survey 11/17/08

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 5/8" iron rod, L.S. 3586, per 16 R.S. 33, lying on the ground. Found 1" iron
pipe 50' witness corners North, South, East, West. All Witness corners were bent.
The South, East and West witness corners were spun and the straight part of the pipe
was used to reestablish the section corner. The North witness was disturbed beyond use.


A description of the physical condition of the monument as found and as set or reset: _____

See Page 2 of 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the land Surveyors' Act on December 15th, 2008.

Signed Duane J. Andrews P.L.S. No.: 4052



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 30, 2008 and examined
 and filed JANUARY 23, 2009.

Signed J. Steven Reichmuth P.L.S. or ~~P.S.~~ No.: 4895

Title Dep. Co. Surveyor

County Surveyor's Comment _____





0 5 10 15 20



SCALE: 1" = 20'

T.7S. R.14E. SECTION 1

T.7S. R.15E. SECTION 6

T.7S. R.14E. SECTION 12

T.7S. R.15E. SECTION 7

50.00' & (R)

50.00' & (R)

50.00' & (R)

LEGEND

- Found 1" Iron Pipe witness corner per 16 R.S. 33.
- Set 3/4" Iron Pipe, L.S. 4052 flush, built rock mound around it.
- (R) Record Information per 16 R.S. 33