

CORNER RECORD

Document Number 3590 D

City of _____ County of MERCED, California

Brief Legal Description N.E. 1/16 COR. SECT. 22, T.7S., R.10E., MDMA.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 2-4-92

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: 5/8" IRON PIN IN MONUMENT WELL. CALTRANS DID NOT ACCEPT AS 1/16 CORNER. ONLY MARKINGS ON 1 1/2" CAP ON PIN IS 12260.

A description of the physical condition of the monument as found and as set or reset: MON. IN GOOD CONDITION IN UNCAPPED MONUMENT WELL DOWN 0' 15"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Feb. 4 1992.

Signed Rafael Schaal L.S. or R.C.E. Number LS3730



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3-13- 1992 and examined and filed 3-20- 1992.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment _____

N. ~~1/4~~ 1/16 COR.
 SECT. 22, T. 7S. R. 10E. MOBBEN
 (NOT ACCEPTED BY CALTRANS
 AS 1/16 COR.)

