

CORNER RECORD

Document Number 3654

City of _____ County of MERCED, California

Brief Legal Description N.W. COR. LOT 34, MILLER & LOX Subd. SEC. 26 10/10



CORNER TYPE

COORDINATES (Optional)

Government Corner Control N. _____
 Meander Property E. _____
 Rancho Other LOT COR. Zone _____ Datum _____
 Date of Survey _____ Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Monument shown on Record of Survey shows 1/4" iron cap
FD. 1/2" rod (SEE REVERSE SIDE FOR SWING TIES)
POINT TIED OUT NOVEMBER 1996 PRIOR TO PAVING EFFORT BY MERCED
COUNTY. (MONUMENT WELL SET AFTER PAVING)

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR
THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM
IS MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN
HEREON TO TRUE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.


Signed Roy L. Turney L.S. or R.E. Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

