


**CORNER RECORD**

Document Number 3719

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N 1/4 CORNER SECTION 8, T.6S., R. 11 E., M.D.B. & M.



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 3-26-09

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2 1/2" IRON PIPE WITH BRASS CAP IN MONUMENT WELL AS SHOWN ON RECORD OF SURVEY RECORDED IN VOLUME 18 OF RECORD OF SURVEYS AT PAGES 46 THROUGH 53, MERCED COUNTY RECORDS.

A description of the physical condition of the monument as found and as set or reset: LEFT AS FOUND, MAY BE DESTROYED DURING CONSTRUCTION PROJECT.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 6, 2009

Signed [Signature] P.L.S or R.G.E. No. 7621



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received April 6, 2009

and examined and filed April 9, 2009

Signed [Signature] P.L.S or ~~R.G.E.~~ No. 4895

Title Dep. County Surveyor

County Surveyor's Comment \_\_\_\_\_



