


CORNER RECORD

Document Number 3743(2)

City of _____ County of Merced, California

Brief Legal Description East 1/4 Sec. 35, T. 9 S. R. 10 E., M. D. B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 02-08-2013

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 2.5" Brass Disk set in 1" Iron Pipe, down 0.9' in monument well.

The Brass Disk is stamped: "Department of Interior U.S. Bureau of

Reclamation 1/4 S35:S36 1965" per Corner Record #3743. Monument is located

in the center of SR-165 about a half mile North of Henry Miller Road and


approximately 950' North of the intersection of Santa Fe Grade Road.

A description of the physical condition of the monument as found and as set or reset: Monument was found in
good condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on MARCH 21 2013

Signed Bradley D. Buller P.L.S or R.C.E. No. L 7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 21, 2013
and examined and filed April 4, 2013

Signed J. Steven Reichmuth P.L.S or R.C.E. No. 4895

Title Acting County Surveyor



County Surveyor's Comment _____

E. 1/4 COR. OF SEC. 35 T. 9 S., R. 10 E.

