


CORNER RECORD

Document Number 3776

City of _____ County of MERCED, California

Brief Legal Description S.E. COR. SEC. 11, T. 10 S. R. 11 E.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Monument called 3/4" I.P. on Parcel Map BK. 73 Pg. 2
and 1 1/2" I.P. in Field BK. 701 Pg. 12
Monument well set over 1" iron pipe (SEE REVERSE SIDE FOR SWING TIES) POINT TIED OUT NOVEMBER 1996 PRIOR TO PAVING EFFORT BY MERCED COUNTY.

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM IS MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN HEREON TO THE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.

Signed Roy L. Turney L.S. or ~~P.C.~~ Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

T. 10 S. R. 11 E.

CAL. DIV. HWYS.
TAG. IN POWER
POLE

WELL

179.2'

SEC. 11

SEC. 12
FD. 1" I.P.
down 0.60
SEC. COR.

31.52'

SET 11" X 12" I.P. ON
DITCH BANK R.P.

Monument Well
Set over Monument

SEC. 14

DEEP

SEC. 13