


CORNER RECORD

Document Number 3832

City of _____ County of MERCED, California

Brief Legal Description EAST 1/4 COR. SECT. 17, T.10S. R.11E. MD. B&M



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6-20-90

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FD. 3x3 REDWOOD POST WITH RUSTED OUT NAIL IN TOP. SET 3/8" x 8" SPIKE TO REPLACE NAIL. SEE STATE HWY MAP 10MER 152 PG 4 OF 47

A description of the physical condition of the monument as found and as set or reset: POST SOFT BUT STILL GOOD CONDITION - REPLACED NAIL WITH 3/8" SPIKE - DOWN 0.6"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 20 1990.

Signed Ralph N. Scheel, Jr. L.S. or R.C.E. Number LS 3730 LIC EXP 6-30-92



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor

County Surveyor's Comment COR. # 3832



17-16

T. 105. R. 11 E.
M. D. B. & M.

