


CORNER RECORD

Document Number 3937

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N.E. COR. SEC. 11, T. 10 S. R. 11 E



CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Monument agrees with Parcel Map Bk. 73 Pg. 2 and  
County Field Bk. 701 Pg. 12  
Monument well set over 3" X 3" with 1/2" I.R. ON NORTH SIDE  
(SEE REVERSE SIDE FOR SWING TIES) POINT TIED OUT NOVEMBER, 1936  
PRIOR TO PAVING EFFORT BY MERCED COUNTY

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR  
THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM  
IS MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN  
HEREON TO THE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16, 1997.

Signed Roy L. Turney L.S. or R.C.E. Number 5523

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.

County Surveyor's Comment \_\_\_\_\_



T. 10 S. R. 11 E

SEC. 4

SEC. 3

FO. 3" x 3" R/W. POST.  
SEC. COR. 1/2" Rod north side  
Monument Well Set  
over Monument

NAIL & CAP IN  
POWER POLE

27.03

END OF PAVEMENT  
DOWN 0.80

FENCE

FO - 0 - 0

46FF

FOURTH POST

SEC. 9

SEC. 10

DEEP WELL RD.