


CORNER RECORD

Document Number 4051

City of _____ County of MERCED, California

Brief Legal Description E. 1/4 COR. SEC. 15, T. 11 S., R. 10 E.



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Monument agrees with Parcel Map 45 P6. 25.
FD 3/4" I.P. @ SURFACE TIED OUT NOVEMBER 1996 DUE TO PAVING
EFFORT BY MERCED COUNTY. JANUARY 15, 1997 3/4" I.P. DESTROYED
RESET 1" I.P. TAGGED COUNTY SURVEYOR. IN MONUMENT WELL.
(SEE REVERSE SIDE FOR TIES)


A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR

THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM
IS MADE AS TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN
HEREON TO TRUE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.

Signed Roy L. Turney L.S. or ~~REG.~~ Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

1-14-97

T. 11 S. R. 10 E.



AVE.

CENTER

FD. 3/4" I.P. AT SURFACE 1/4 COR. 3/4" I.P. Destroyed County Surveyors Tag SEC. 15

Set 2"x2" W/NAIL → 25.50

Reset 1" I.P. with County Surveyors Tag

42.17

66.35'

NAIL & SHINER IN 12" φ WALNUT TREE

SEC. 14

NAIL & SHINER IN 8" φ WALNUT