


CORNER RECORD

Document Number 4111

City of _____ County of MERCED, California

Brief Legal Description NORTH 1/4 Corner Section 2, 9/8

COTTONWOOD



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Monument agrees with Record of Survey Vol. 9 Pg. 38
Monument well set over 1.5" iron pipe (SEE REVERSE SIDE FOR TIES)
POINT TIED OUT NOVEMBER 1996 PRIOR TO PAVING EFFORT BY
MERCED COUNTY

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR
THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM
IS MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN
HEREON TO THE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.


Signed Roy L. Turney L.S. or R.C.E. Number 5523

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP CO. SUR.

County Surveyor's Comment _____



OK 1-14-97



Monument Well set over
Fd. 1" I.P. down 0.6'
N. 1/4 COR. SEC. 2 9/8

NAIL & SHINER IN
SERVICE POLE

42.88'

SEC. 35 T. 8 S. R. 8 E

COTTONWOOD

ROAD

SEC. 2 T. 9 S. R. 8 E

46.64'

32.92'

NAIL & SHINER IN
SERVICE POLE

NAIL & SHINER IN
TEL. POLE

GRAVEL LANE