


CORNER RECORD

Document Number 4112

City of \_\_\_\_\_

County of MERCED, California

Brief Legal Description 1/4 Cor. Between Secs, 34 & 35, T.10 S. R. 10 E.



CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Monument agrees with Parcel Map BK. 37 Pg. 50  
FOUND 3/4" I.P. @ SURFACE TIED OUT NOVEMBER 1996 DUE TO PAVING EFFORT  
BY MERCED COUNTY. JANUARY 14, 1997 3/4" I.P. DESTROYED RESET WITH  
1" I.P. TAGGED COUNTY SURVEYOR IN MONUMENT WELL.  
(SEE REVERSE SIDE FOR SWING TIES)

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE FOR  
THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO CLAIM IS  
MADE AS TO THE RELATIONSHIP OF THE POINT OR LINE SHOWN HEREON  
TO TRUE BOUNDARY LOCATIONS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 16 1997.

Signed Roy L. Turney L.S. or R.C.E. Number 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 16 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_

OK 1-14-97

