


CORNER RECORD

Agency Index 4277

Document Number _____

City of _____ County of MERCED, CaliforniaBrief Legal Description S. 1/4 COR. SECTION 33 T.9S. R.11E. MDB&M.**CORNER TYPE****COORDINATES (Optional)**

9
T. ~~10~~S., R. 11E.

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey MARCH 20, 2019

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____


 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902PLS Act Ref.: 8765(d) 8771 8773 Other:Corner/Monument: Left as found Established Rebuilt Pre-Construction Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

 See sheet #2 for description(s):*MONUMENT MAY BE DISTURBED DUE TO CONSTRUCTION***SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on August 6, 2019Signed [Signature] P.L.S. or R.C.E. No. 9417**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received AUGUST 7, 2019and examined and filed AUGUST 16, 2019Signed Zach T. Janz P.L.S. or R.C.E. No. 8664Title COUNTY SURVEYOR**County Surveyor's Comment**



SCALE: 1" = 30'

S.W. 1/4
SECTION 33
T.9S. R.11E.

PORTION
SECTION 33
T.9S. R.11E.

FOUND CUT X IN CONCRETE
PER 59-R.S.-2, M.C.R.

CANAL

FOUND CUT X IN CONCRETE
PER 59-R.S.-2, M.C.R.

CANAL

FOUND CUT X IN CONCRETE
PER 59-R.S.-2, M.C.R.

SOUTH 1/4 CORNER SECTION 33
FOUND 1 1/2" IRON PIPE WITH NO TAG.
PER 59-R.S.-2, M.C.R..

T.9S.
T.10S.

T.9S.
T.10S.

HENRY MILLER AVENUE

NORTH 1/2
SECTION 4
T.10S. R.11E.

SET 80D NAIL

49.94'

36.47'

44.03'

41.20'