


CORNER RECORD

Document Number 236

City of _____ County of MERCED, California

Brief Legal Description SECTION COR. COMMON TO SEC. 35 & 36 T. 6 S., R. 11 E. & SEC. 1 & 2 T. 7 S., R. 11 E. M.D.B. & M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-14-95

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
USED CORNER TIES FOUND IN ^{B.C-A} COUNTY FIELD BOOK 618 PAGE 8.

A description of the physical condition of the monument as found and as set or reset:
RESET 3/4" IRON PIPE W/ R.C.E. 10990 TAG, 6" DOWN IN MONUMENT WELL.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on SEPT. 18 1995.


Signed James W. Jolladay L.S. or R.C.E. Number RCE 10990



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT 1995 and examined and filed SEPT. 22 1995.

Signed Roy L. Turney Title DEPUTY CO. SUR.



County Surveyor's Comment Ties agree with corner record on file at the County Surveyors Office date 10-3-91

