


CORNER RECORD

Document Number 305

City of _____ County of MERCED, California

Brief Legal Description S.W. CORNER SECTION 34, T. 6 S., R. 13 E., M. B. B. & M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-9-2008

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPE WITH L.S. 3733 TAG AS SHOWN ON 50 P.M. Co, M.C.R.

CORNER MAY BE DESTROYED WITH COUNTY ROAD PROJECT

A description of the physical condition of the monument as found and as set or reset: _____


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on SEPT. 10, 2008
 Signed David D. Heinrichs P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 11, 2008
 and examined and filed Sept. 30, 2008
 Signed J. Steven Reichmuth P.L.S. or R.C.E. No. 4895
 Title Dep. County Surveyor



County Surveyor's Comment _____

