


CORNER RECORD

Document Number 305

City of _____ County of MERCED, California

Brief Legal Description S.W. CORNER SECTION 34, T.6S., R.13E., M.D.B. & M.



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 11-13-2008

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED CORNER FROM TIES FOUND ON CORNER RECORD # 305

A description of the physical condition of the monument as found and as set or reset: SET 3/4" IRON PIPE WITH C.S. 7621 TAG IN MONUMENT WELL.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Dec. 23, 2008
 Signed David D. Heinrich P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 23, 2008
 and examined and filed January 6, 2009
 Signed J. Steven Reichmuth P.L.S. or R.C.E. No. 4895
 Title Dep. Co. Surveyor



County Surveyor's Comment _____

