


CORNER RECORD

Document Number 306

City of _____ County of MERCED, California

Brief Legal Description S.W. CORNER SECTION 3, T. 15, R. 13 E., M.D.B. & M.



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 11-13-2008

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED CORNER FROM TIES FOUND ON CORNER RECORD # 306 .

A description of the physical condition of the monument as found and as set or reset: SET 3/4" IRON PIPE WITH L.S. 7621 TAG IN MONUMENT WELL.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on DEC. 23, 2008

Signed [Signature] P.L.S or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 23, 2008

and examined and filed January 6, 2009

Signed [Signature] P.L.S or R.C.E. No. 4895

Title Dep. County Surveyor



County Surveyor's Comment _____

