

CORNER RECORD


Document Number 306

City of _____

County of MERCED, California

Brief Legal Description S.W. CORNER SECTION 3, T. 7S., R. 13 E., M.D.B. & M.

T. 7S., R. 13E



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 9-9-2008

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPE IN MONUMENT WELL WITH L.S. 3733
TAG AS SHOWN ON 24 R.S. 14, M.C.R.

MONUMENT MAY BE DESTROYED WITH COUNTY ROAD PROJECT

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on SEPT. 10, 2008
Signed [Signature] P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 11, 2008
and examined and filed Sept. 30, 2008
Signed [Signature] P.L.S. or R.C.E. No. 4895
Title Dep. County Surveyor



County Surveyor's Comment _____

