


CORNER RECORD

Document Number 360

City of _____ County of MERCED, California

Brief Legal Description NORTHWEST QUARTER, SECTION 20, T.8S., R.9E. M.D. B.E.M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/13/00

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner -- Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 1" IRON PIPE WITH YELLOW PLUG L.S. 5323 DOWN 0.270 m, NO REFERENCE

A description of the physical condition of the monument as found and as set or reset: MONUMENT IS IN GOOD CONDITION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 7/13/2000

Signed Ginger J. Rubino (L.S.) or R.C.E. Number 6396 Expires 12/31/2002



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 28 2000 and examined and filed AUG. 11 2000

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

