


CORNER RECORD

Document Number 431-Q

City of _____ County of MERCED, California

Brief Legal Description Lot 28 3 O.P. 26 M.C.R.



6/10

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8-10-06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner -- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE SKETCH


A description of the physical condition of the monument as found and as set or reset:

SEE SKETCH

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 9-8-06

Signed [Signature] P.L.S or R.C.E. No. _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 11, 2006

and examined and filed Sept. 18, 2006

Signed [Signature] P.L.S or R.C.E. No. 4895

Title Dep. County Surveyor



County Surveyor's Comment _____



- REFERENCES**
- (1) The Denafr Land and Development Company's Colony No. 3, 3 O.P. 26, M.C.R.
 - (2) Parcel Map for Samuel O. Pierce, 16 P.M. 19, M.C.R.
 - (3) Parcel Map for Jesse Yohannan, 14 P.M. 8, M.C.R.
 - (4) Record of Survey, 13 R.S. 4, M.C.R.
 - (5) "The Links", 39 O.P. 37, M.C.R.

- LEGEND**
- Found and accepted monument as indicated
 - Set 3/4" iron pipe, L.S. 4403

BASIS OF BEARINGS

N. 89°20'00" E. for the centerline of Johnson Avenue as shown on the Map of the Denafr Land and Development Company's Colony No. 3, Volume 3, Official Plats, Page 26, Merced County Records.

