


CORNER RECORD

COUNTY OF Merced T. 8S. R. 15E. M.D.B. MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT May 17 1983



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


*Found 2" inside diameter iron pipe 1st feet down.
 Found by using ties in field book "F.A.S. 555 (3) Alignment,
 Culture" page 1*

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

*Set a 1" inside diameter iron pipe over the 2" iron pipe.
 Set a survey encasement around the 1" iron pipe
 and tagged "County Surveyor."*

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



*Prepared by
 Gary Grinder
 Ties in F.B. "F.A.S.
 555 (3) Alignment,
 Culture" page 1
 Gary Grinder*

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____.

BY: [Signature]

TITLE: County Surveyor

DOCUMENT No. 455

STATEMENT ON BACK OF SHEET

YES NO