


CORNER RECORD

Document Number 578

City of \_\_\_\_\_

County of MERCED, California

Brief Legal Description S.E. COR. SEC. 17 1/2



CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey 8-11-92

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FD 1 1/2" I.P. IN MON. BOX

BK 658-19

A description of the physical condition of the monument as found and as set or reset:

O.K. - 8-30-93

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 7 19 93.

Signed Lawrence L. Bowers L.S. or R.C.E. Number \_\_\_\_\_



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT. 19 93 and examined and filed SEPT. 16 19 93.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment See P.M. - 37 - Pg. 15

92404.07

SEC 17

SEC 16

SET 3/4" I.P., BLANK TAG,  
7' N. OF N. E.P. OF  
EXISTING ROAD.

SET NAIL & SHINER  
IN W. SIDE TELE. POLE

FD. 1 1/2" I.P. IN MON. BOX,  
NO TAG, SE COR. OF  
SEC. 17 1/2.

EAST

AVENUE

SET NAIL & SHINER  
IN SE SIDE POWER  
POLE. DO NOT USE  
FD. NAIL & SHINER  
IN NW SIDE AS  
IT IS A POOR ANGLE  
TO MON.

SET NAIL & SHINER  
IN W. SIDE OF FENCE  
COR. POST. (6" x 4").

DIRT / GRAVEL ROAD.

SEC 20

SEC 21

POINTS WERE TIED OUT PRIOR TO PAVING  
EFFORT BY MERCED COUNTY DEPARTMENT  
OF PUBLIC WORKS