

**CORNER RECORD**

Document Number 638-W

City of Planada

County of Merced, California

Brief Legal Description Intersection - Fancher & Stanford, north & south



7/15

**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Existing monuments were removed in paving project. They were not intended to be removed. Reestablished as shown, based on control as set for repaving project.

A description of the physical condition of the monument as found and as set or reset:


Set 3/4" Iron Pipe in monument well, L.S. 3733

B-C-A F.B. 731, page 25

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 8 2003

Signed [Signature] P.L.S or R.C.E. No. L.S. 3733




**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received APRIL 10, 2003

and examined and filed APRIL 29, 2003

Signed [Signature] P.L.S or R.C.E. No. 5523

Title Dep. Co. Surveyor



County Surveyor's Comment \_\_\_\_\_

HASKELL AVE

#3 10.3/4 P.O.  
D.V. 0.2

16.785  
(390.0)  
N 0.08 09 M 389.91

589.91 MEAS  
28.685

STANFORD  
589.58 W

570.07  
570.07 TOPO

#7

3.17 #6

17.50 P.C

384.67  
370.1  
394.57

Topo

4-3 785.02  
1-3 389.91  
1-7 395.10  
~~785.02~~

~~375.11  
370.1  
394.57~~

CABELLO

#2 P.O. 1/2" - 1.1 P  
IN TON. BOX

589.51 P

~~389.91  
395.10  
394.83  
784.65~~

ED

Topo

389.82

394.83

784.65

N 389.91

S 395.10

784.65