


CORNER RECORD

Document Number 724-B

City of MERCED

County of MERCED, California

Brief Legal Description CENTERLINE MONUMENT W. 18<sup>TH</sup> AND M.L.K. PER 17-RS-48



T. 7 S.  
R. 14 E.

CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 9/5/2011

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENT AND TIED TO REFERENCE POINTS PRIOR TO CONSTRUCTION

A description of the physical condition of the monument as found and as set or reset:

FOUND 5/8" ROD IN MONUMENT WELL DESTROYED BY CONSTRUCTION

SET 3/4" I.D. IRON PIPE TAGGED LS 8001 IN MONUMENT WELL

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 11/7/2011

Signed J. S. Conti P.L.S or R.C.E. No. LS 8001



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 10, 2011

and examined and filed November 15, 2011

Signed J. Steven Reichmuth P.L.S or R.C.E. No. 4895

Title Deputy County Surveyor



County Surveyor's Comment \_\_\_\_\_

