


# CORNER RECORD

Agency Index 880  
 Document Number \_\_\_\_\_

City of Unincorporated County of Merced, California  
 Brief Legal Description Corner Common to Sections 7,8,17,and 18 T9S; R9E; MD Base and Meridian

**CORNER TYPE** **COORDINATES (Optional)**



- Government Corner  Control
- Meander  Property
- Rancho  Other

N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units  Metric  U.S. Survey Foot  
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

Date of Survey September 30, 2018

- PLS Act Ref.:  8765(d)  8771  8773  Other:
- Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
 See sheet #2 for description(s):

Found 3/4" O.D. Iron Pipe with Plastic Plug not readable in monument well. In the Intersection of (SR-33) and Husman Road. Per County Recorder County Record Document 880, 880 (2) and 880 (3).

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyors' Act on October 30, 2018  
 Signed Bradley Buller P.L.S. or R.C.E. No. L 7659



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received NOVEMBER 30, 2018  
 and examined and filed DECEMBER 28, 2018  
 Signed Zach T. Janz P.L.S. or R.C.E. No. 8664  
 Title COUNTY SURVEYOR  
 County Surveyor's Comment \_\_\_\_\_



