


CORNER RECORD

Agency Index 880
Document Number _____

City of Unincorporated County of Merced, California
Brief Legal Description Corner Common to Sections 7,8,17,and 18 T9S; R9E; MD Base and Meridian

CORNER TYPE

COORDINATES (Optional)



- Government Corner Control
 Meander Property
 Rancho Other

N. _____ E. _____
 Elevation _____
 Units Metric U.S. Survey Foot
 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

Date of Survey September 30, 2018

PLS Act Ref.: 8765(d) 8771 8773 Other:
 Corner/
 Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction


Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 3/4" O. D. Iron Pipe with Plastic Plug unreadable down .5' in a monument well. In the Intersection (SR-33) and Husman Road. Per County Corner Record, Document 880, 880 (2) and 880 (3).

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on October 30, 2018
 Signed Bradley D. Buller P.L.S. or R.C.E. No. L 7659



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 30, 2018
 and examined and filed DECEMBER 28, 2018
 Signed Zachary T. Janz P.L.S. or R.C.E. No. 8664
 Title COUNTY SURVEYOR
 County Surveyor's Comment _____



