


# CORNER RECORD

Agency Index 881  
 Document Number \_\_\_\_\_

City of \_\_\_\_\_ Unincorporated \_\_\_\_\_ County of Merced, California  
 Brief Legal Description East 1/4 Corner Section 18; T9S; R9E; Mount Diablo Base and Meridian



### CORNER TYPE

- Government Corner     Control  
 Meander                       Property  
 Rancho                             Other

Date of Survey October 1, 2018

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units     Metric             U.S. Survey Foot  
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902


PLS Act Ref.:     8765(d)             8771             8773             Other:  
 Corner/  
 Monument:     Left as found             Established             Rebuilt             Pre-Construction  
 Found and tagged             Reestablished             Referenced             Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:  
 See sheet #2 for description(s):

Found 1/2" Iron Pipe with Orange Plastic Plug Stamped "LS 3664" down 0.45' in a monument well in the Intersection of (SR-33) and Hulen Road. Per County Recorder Corner Record, Document 881.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyors' Act on October 30, 2018  
 Signed Bradley D. Buller P.L.S. or R.C.E. No. L 7659



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 30, 2018  
 and examined and filed DECEMBER 28, 2018  
 Signed Zachary T. Janz P.L.S. or R.C.E. No. 8664  
 Title COUNTY SURVEYOR

County Surveyor's Comment



