


CORNER RECORD

DPD-3011A (Rev. 3/98) CT# 7541-4554-2

Document Number 892

City of _____ County of Merced, California

Brief Legal Description Northeast corner of Section 26, T7S, R12E, MDB & M. State Hwy 140 at Applegate Road.



CORNER TYPE

COORDINATES(Optional)

Government Corner Control
Meander Property
Rancho Other

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vert. Datum: NGVD29 NAV88
Meas. Units: Metric Imperial

Date of Survey June 3, 2000

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4 inch I.D. iron pipe with rebar. Down 0.8 feet. No tag.

Found as per Record of Survey Vol. 59 pages 44 & 45, Sept. 29, 1987 Merced County Records.

Pipe found with remaining County ties and 2' RP's North & East.

A description of the physical condition of the monument as found and as set or reset: _____

Left as found. Made new ties. (See page 2)


Note: Caltrans has a scheduled project to AC Overlay Route 140. After construction a standard Caltrans monument well is to be set at Section Corner.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on June 15, 2000.

Signed Kevin Gordon Matthesen P.L.S. Number 5943 - Expires 12/31/00
For the State of California
Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 3, 2000 and examined

and filed JULY 21, 2000.

Signed Roy L. Turney P.L.S. or R.C.E. Number 5523

Title DEP. CO. SURVEYOR

County Surveyor's Comment _____



NORTHEAST CORNER SECTION 26 T7S, R12E, M. D. B. & M.

