


NO. 95

CORNER RECORD

COUNTY OF MERCED T. BS. R. 17E. M.D.B. & MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT JUNE 22 19 77



NORTH WEST CORNER SECTION 32
BAXTER ROAD (NORTH & SOUTH).
BUCHANAN HOLLOW ROAD (EAST & WEST).

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 2" IRON PIPE - 8" DOWN.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

I TAGGED L.S. 2737

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

41.00' NW OF O IN JCT POWER POLE.
42.49' SW OF O IN FENCE CORNER.
42.78' SW OF 2" I.P. - MARKED COR. - 12" UP.
42.42' SE OF 2" I.P. - MARKED COR. - 12" UP.
62.48' SE OF O IN TEL. POLE.
42.55' NE OF 2" I.P. - MARKED COR. - 12" UP.
J.N. 77-109 F.B. 547 p. 48

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON AUGUST 15 19 77.

SIGNED: William O. Gentry
L.S. or R.C.E. No.:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No. 951

STATEMENT ON BACK OF SHEET

YES NO