


**CORNER RECORD**

Document Number 1047

City of \_\_\_\_\_ County of Merced, California

Brief Legal Description S.E. Corner Section 15 5/15



**CORNER TYPE**

**COORDINATES  
(Optional)**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 8-12-92

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

Fd. 3/4" Iron Pipe

Monument well was set over existing monument 8-30-93

F.B. 658-24

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 7 19 93.


Signed [Signature] L.S. or R.C.E. Number \_\_\_\_\_



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPT. 19 93 and examined and filed SEPT. 16, 19 93.

Signed [Signature] Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SEC. 15

SEC 14

FD. NAIL & SHINER  
IN E. ± SIDE POWER  
POLE.

HALL ROAD



SET 3/4" I.P. WITH  
BLANK TAG.

93.48'

56.68'

FD. 3/4" I.P., NO TAG,  
THIS IS SUPPOSED TO  
BE OVER A CONC. MON.  
SE COR. OF SEC. 15 1/4.

Monument well set over  
3/4" I.P.

EAST

AVENUE

36.51'

37.29'

SET 3/4" I.P., WITH  
BLANK TAG; 5' N.  
& 5' W. OF UPRIGHT  
TELE. BOX.

FD. NAIL & SHINER  
IN NE SIDE OF POWER  
POLE.

SEC 22

POINTS WERE TIED OUT PRIOR TO PAVING  
EFFORT BY MERCED COUNTY DEPARTMENT  
OF PUBLIC WORKS

SEC 23