

CORNER RECORD

Document Number 1057-2

City of MERCED

County of MERCED, California

Brief Legal Description LINE BETWEEN LOTS 62 & 63 OF 20 O.P. 49-54, M.C.R.



T95, R13E

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED THE WEST CORNER COMMON TO LOTS 62 & 63
20 O.P. 49-54, M.C.R. PER CORNER RECORD No. 1057-2
ON FILE WITH MERCED COUNTY SURVEYOR'S OFFICE

A description of the physical condition of the monument as found and as set or reset:
SET 3/4" IRON PIPE w/ L.S. 7621 TAG.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on FEBRUARY 6, 2002
Signed David D. Heinrichs P.L.S. or R.C.E. No. 7621



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-6-02
and examined and filed 2-6-02
Signed Roy L. Turney P.L.S. or R.C.E. No. 5523
Title DEP. CO. SURVEYOR



County Surveyor's Comment NONE

