


CORNER RECORD

Document Number 1067

City of _____ County of Merced, California

Brief Legal Description N.E. Corner Section 19 T. 7S., R. 16E



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey 4-26-91

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found nail & tin on surface, tied then removed. Magnetic indication of iron ± 2.0' deep, did not recover.

Ties shown hereon are to nail & tin and do not represent a usable corner.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 10-1 1991.
 Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10-2- 1991 and examined and filed 10-3- 1991.
 Signed [Signature] Title Dep Co Sur



County Surveyor's Comment _____

