


CORNER RECORD

Document Number 1351-P(2)

City of _____ County of Merced, California

Brief Legal Description Witness Corner to Southwest Corner of Section 14 T.75/R.14E.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey November 26, 2012

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found 2" O.D. iron pipe 20' north of the Southwest corner of Section 14 T.75, R. 14 E. per Merced County Field Book 315 pg 59. Set Monument well over pipe. Verified position using ties shown on Corner Record No. 1351-P dated Oct. 3, 2012.

A description of the physical condition of the monument as found and as set or reset: See page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 2, 2013

Signed [Signature] P.L.S or ~~P.C.E.~~ No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 2, 2013

and examined and filed April 4, 2013

Signed [Signature] P.L.S or ~~P.C.E.~~ No. 4895

Title Acting County Surveyor



County Surveyor's Comment _____

