


# CORNER RECORD

Document Number 1370-22 ok

City of MERCED County of MERCED, California

Brief Legal Description SOUTHEASTERLY CORNER OF PARCEL "A" OF 35 PM 9. M.C.R.



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 10-10-96

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish the corner:  
FOUND PROPERTY CORNER PER BOOK 35 OF PARCEL MAPS AT PAGE 9. M.C.R.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
FOUND 3/4" IRON PIPE UP 2". NO TAG. DESTROYED BY STREET CONSTRUCTION  
SET NEW 1-1/2" IRON PIPE TAGGED "LS 5503" DOWN 8"


### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on OCTOBER 11 19 96.  
Signed *Cris H. Robles* L.S. or R.C.E. Number L.S. 5503



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov 19 96 and examined and filed 11-18 19 96.  
Signed *Roy L. Turney* Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_

