


CORNER RECORD

Document Number 1402

City of Unincorporated area of Stevenson Ca. County of Merced, California

Brief Legal Description North West Corner Section 7 T7 R10



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey October 15 2004

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Section Corner References used Field Book 710 pg 54 Merced County public Works. Book 36 Record of Survey Page 1

A description of the physical condition of the monument as found and as set or reset:

Found 2 1/2" brass cap, -9" below River Road paving. January 21, 2005 set 6 1/2 x 9" metal monument centered over brass cap. Used Sacked Cement as back fill around cylinder. Left in good condition. Set 2 RPs in 4 Quadrants. No distant RP set.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on January 24 2005

Signed J E Coplantz P.L.S or R.C.E. No. 3664

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-26-05

and examined and filed 2-7-05

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

Title Dep. Co. Surveyor

County Surveyor's Comment \_\_\_\_\_

