


CORNER RECORD

Document Number 1596-G

City of _____ County of Merced, California

Brief Legal Description NE Corner of Lot 21, Banker-Virtue-Davis Colony, YOP 40



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey October 3, 2012

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1 3/4" ID. iron pipe, approximately 2' down per unrecorded survey 5-362. Tied out prior to reconstruction of Givens Lustre Road.

A description of the physical condition of the monument as found and as set or reset: See page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on November 16, 2012

Signed [Signature] P.L.S or ~~P.C.E.~~ No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 16, 2012

and examined and filed November 16, 2012.

Signed [Signature] P.L.S or ~~P.C.E.~~ No. 4895

Title Acting County Surveyor



County Surveyor's Comment _____

