


CORNER RECORD

Document Number 1857 (2)

City of _____ County of Merced, California

Brief Legal Description Southwest Corner of Section 14 T.7S., R.14E.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey November 26, 2012

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Monument destroyed by road reconstruction. Set 1" iron pipe tagged "Merced Co. Surveyor" in monument well using ties set on corner record 1857 dated October 3, 2012

A description of the physical condition of the monument as found and as set or reset: See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 2, 2013

Signed [Signature] P.L.S or P.C.E. No. 4895



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 2, 2013

and examined and filed April 4, 2013

Signed [Signature] P.L.S or P.C.E. No. 4895

Title Acting County Surveyor



County Surveyor's Comment _____

