


CORNER RECORD

Document Number 1979

City of _____

County of MERCED, California

Brief Legal Description N.W. CORNER OF SECTION 36, T. 9 S., R. 13 E.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey NOV. 1999

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FD. 2" IRON PIPE WITH TAG R.C.E. 13760 IN SURVEY ENCASEMENT.

A description of the physical condition of the monument as found and as set or reset:
SET NEW TIES PRIOR TO WASHINGTON ROAD OVERLAY (SEE BACK OF THIS SHEET)
SURVEY ENCASEMENT WAS RAISED TO ~~R~~ GRADE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DEC 1999

Signed Roy L. Turney P.L.S or R.C.E. No. 5523



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 1999

and examined and filed JAW 2000

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

Title DEPT CO. SURVEYOR



County Surveyor's Comment _____



SECTION 26

SECTION 25

WASHINGTON

ROAD

SEC. LINE

FENCE POST WITH NAIL & TIN

NAIL & TIN IN POWER POLE

56.33'

29.08'

SECTION CORNER.
2" IRON PIPE W/TAG
RCE 13760, IN SURVEY ENCASEMENT

46.83'

2' TALL FENCE POST WITH NAIL & TIN

SECTION 35

SECTION 36

T. 9 S., R. 13 E.