


No. 222

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION — DATE OF VISIT September 20, 1976



Northwest Corner, Section 5.

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found traces of old fence line to the South indicated in Merced County field book of a 1930 survey.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1" O.D. x 28" galvanized iron pipe tagged L.S. 4156 at 0.5 feet below road surface at the intersection of the old fence line and the North line of Section 5 9/15.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 36.95 Northwest from nail & shiner in power pole.
65.66 Southeast from nail & shiner in railroad tie fence post.
84.26 Southeast from nail & shiner in power pole.
Set 2.00 feet shiners South & East.



JOHNNY E. SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 30, 1979

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED Feb. 25 1980 AND EXAMINED AND FILED BY: Walt Mitchell TITLE: DOCUMENT No. 2227 STATEMENT ON BACK OF SHEET YES [] NO []

SEAL