


CORNER RECORD

COUNTY OF MERCED, CALIFORNIA

SECTION 23 TOWNSHIP 10 South RANGE 10 East M.D.B. & M.

BRIEF LEGAL DESCRIPTION: Lot 11 as shown on Map of W.M. Roberts, Resubdivision of Lots 6, and 9, recorded January 7, 1936 in Volume 9 of Official Plats at Page 43, Merced County Records.



CORNER TYPE:

COORDINATES

GOV'T CORNER CONTROL N. _____
 MEANDER PROPERTY _____
 RANCHO OTHER ZONE _____

DATE OF SURVEY: 6-10-92 ELEV. _____

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE USED TO IDENTIFY THE CORNER _____

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT, PERPETUATED, OR RESET 1-inch O.D. X 28 - inch galvanized iron pipe with plastic plug marked LS 5355, down 0.2-foot below surface, set at the southwest corner of Lot 11, Set lead plug with Tag LS 5355, down 0.4-foot in concrete fence post base at the northeast corner of Lot 11. Set a nail and shiner on top of a 2" X 4" nailed over a 4" X 4" fence post at the northwest corner of Lot 11.

SURVEYOR'S STATEMENT


COUNTY SURVEYOR'S STATEMENT

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 13 July 1992 1992

THIS CORNER RECORD WAS RECEIVED 7 1992
 AND EXAMINED AND FILED 7-22 1992

SIGNED: Chris White
 L.S. OR R.C.E. NO: 5355 EXPIRES 12/31/95

BY: Roy L. Turney
 TITLE: DEPUTY COUNTY SURVEYOR



YES NO SKETCH ON BACK OF SHEET

COUNTY SURVEYOR'S STATEMENT: THERE IS NO RECORD INFORMATION FOUND FOR THE 1 1/8" IRON ROD INDICATED OUT OF POSITION FOR THE N.W. CORNER LOT 11 AND THERE IS NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION IT IS MY OPINION THIS FALL UNDER SECTION 7773 REGULATION 464 (E) WHICH ALLOWS A CORNER TO BE FILED

CORNER RECORD

SKETCH (Include reference tie or witness points, remarks and topo of area)

