


Indexed

# CORNER RECORD

Document Number 2466

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description S 1/4 Corner Section 1 9/15



### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

A description of the physical condition of the monument as found and as set or reset: Found 1 1/2" copper disk with "+", down 1 1/2"

Monument boy set over existing monument.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct 24 1995.


Signed [Signature] L.S. or R.C.E. Number \_\_\_\_\_



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 1995 and examined and filed OCTOBER 30 1995.

Signed [Signature] Title DEP. CO. SUR



County Surveyor's Comment Corner Record calls for 1 3/4" brass shaft

